



3 axis motion control gyroscope

Capacitors Installation


Small change for more servos stability



Cut capacitor leads to the same length.



Insert capacitor leads into positive (red) and negative (black) wire connector. Be sure to have negative lead with black wire.



Insert shrink tube and heat it.



Job done!