

# Assembly note – Diode

Zita board Rev. 1.10

Because the NRF24L01 does not consume always the same current, the original design does not work as expected.  
So, install the diode instead of the resistor like this.

